

OUT59003

multi

P 051937Z
FM NPIC WASHDC
TO RUCSC/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEKDA/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2 AF BARKSDALE AFB LA
BT

SECRET CITE NPIC 7666.

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B 125 WAS USED IN MISSION 8104 FLOWN ON 1 JULY 1966.

PROCESSING WAS ACCOMPLISHED AT BARKSDALE.

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: MINUS DENSITY DOTS LOCATED 1.0" FROM THE INBOARD EDGE ARE SPACED 1.65" APART. EMULSION LIFTS ARE PRESENT ON FRAMES 377, 601, AND 1329. SEVERAL PINHOLES WERE NOTED THROUGHOUT THE MISSION. HANDLING MARKS AND REPAIRED TEARS ARE ASSOCIATED WITH APPROXIMATELY HALF OF THE ULTRASONIC SPLICES WHICH WERE MADE AT THE BEGINNING AND END OF EACH PART. A MANUFACTURING SPLICE EXISTS IN FRAME 1110.

C. 9L SIDE: EDGE STATIC IS PRESENT ALONG THE OUTBOARD EDGE. EMULSION LIFTS WERE NOTED IN FRAMES 0285, 0443, 0744, 0745, 1068, AND 1069. A MANUFACTURER'S SPLICE IS LOCATED IN FRAMES 0388 AND 1506. THE ULTRASONIC SPLICE BETWEEN FRAMES 1515/1516 WAS SEPARATING

AT THE INBOARD EDGE. THE OUTBOARD EDGE WAS ALREADY REPAIRED WITH TAPE. A CREASE TOWARD THE BASE WAS NOTED IN FRAME 1516 AS WERE EMULSION SCRATCHES. AN ULTRASONIC SPLICE WITH ITS ASSOCIATED

6 JUL 1966

DISTRIBUTION

No.	Office	Action
1	Dir	
	CS	
	ADMIN	
	SEC BR	
	P & DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
345	TID	✓
	IAD	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

advance copy
submitted

SECRET

---2---

HANDLING MARKS IS PRESENT BETWEEN FRAMES 1800/1801. MINUS DENSITY SPOTS WHICH WERE APPARENTLY CHEMICALLY INDUCED ARE FOUND IN FRAMES 1683/1684, 1685, 1819, 1830, 1831, 1995, 1996, 1997, AND 1832. PINHOLES WERE NOTED OCCASIONALLY.

D. BOTH SIDES: ROLLER CHATTER AND EDGE FOG ARE PRESENT ALONG BOTH EDGES. THE VERTICAL DOT IS BLOOMED AND SLIGHTLY ENTERS THE FORMAT. THE MISSION IS TITLED FROM 0000 TO 2407 INCLUSIVE.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY IS FAIR DUE TO WEATHER.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS AND HAZE DEGRADE APPROXIMATELY 65 PERCENT OF THE MISSION. GP-1

S E C R E T

-END OF MESSAGE-

1